

Field Safety Notice SBN-CPS-2016-014

CPS / Blood Gas & Electrolytes Version 1 09-Jun-2016

cobas b 123 Sensor Cartridge BG/ISE/GLU/LAC: Interference of PCO2 on Sodium Results in Patient Samples

Instrument/System Affected	cobas b 123 <1>	
	cobas b 123 <2>	
	cobas b 123 <3>	
	cobas b 123 <4>	
Product Name	cobas b 123 Sensor Cartridge BG/ISE/GLU/LAC	
GMMI / Part No Device Identifier	05170478001	
Production Identifier	Lot 21560883 / Serial Numbers 00200276 - 00200787	
(Lot No./Serial No.)		
Type of Action	Field Safety Corrective Action	

Affected lot is not available in Singapore

Dear Valued cobas b 123 Customer,

We regret to inform you about an issue affecting **cobas b** 123 POC systems whereby interference of PCO2 on sodium (Na⁺) results (positive bias) is observed in whole blood samples. The issue occurs when Lot 21560883 with SN 00200276 to SN 00200787 of **cobas b** 123 Sensor Cartridges BG/ISE/GLU/LAC are used.

Users who want to measure sodium must not use **cobas b** 123 Sensor Cartridge BG/ISE/GLU/LAC lot 21560883 with SN 00200276 to 00200787 and must use **cobas b** 123 Sensor Cartridges from unaffected lots.

Whenever a cobas b 123 Sensor Cartridge BG/ISE/GLU/LAC of the affected lot 21560883 - with SN 00200276 to SN 00200787 is used, the parameter sodium (Na⁺) must be deactivated in order to avoid any risk of reporting too high sodium results.



Description of Situation

Recently we have become aware during internal tests that the specific lot 21560883 with SN 00200276 to SN 00200787 of **cobas b** 123 Sensor Cartridge BG/ISE/GLU/LAC show interference of *P*CO2 on sodium results in whole blood samples. The sodium bias increases with the *P*CO2 (partial pressure of carbon dioxide) values of the sample.

The interference of *P*CO2 on sodium in patient samples causes medical risks only for patients with increased *P*CO2, or with *P*CO2 at the very upper end of normal range.

The positive bias of sodium falsifies either:

- hyponatremic values as normal results or
- normal values as hypernatremic results.

In case of false normal results the medical need to treat hyponatremia might be missed. Due to falsely high results above the upper normal range, unnecessary therapeutic body fluid correction might be initiated. However, to date, there are no known cases or complaints where this issue caused any serious adverse events to patients.

Actions taken by Roche Diagnostics

Roche Diagnostics will further investigate this issue in order to implement corrective and preventive actions. Roche has developed a workaround which describes how to deactivate the parameter sodium (see "Appendix 2: Deactivation of sodium [Na⁺]"). Roche Diagnostics will replace affected **cobas b** 123 Sensor Cartridges BG/ISE/GLU/LAC.

Actions to be taken by the Customer/User

Users that want to measure sodium must use unaffected lots of **cobas b** 123 Sensor Cartridges BG/ISE/GLU/LAC. Whenever the affected **cobas b** 123 Sensor Cartridge BG/ISE/GLU/LAC lot 21560883 with SN 00200276 to SN 00200787 is used, the parameter sodium must be deactivated in order to avoid any risk of reporting too high sodium results.

For details regarding detection of the Sensor Lot and Serial Number, see Appendix 1.

For details regarding the deactivation of sodium, see Appendix 2.

cobas b 123 Sensor Cartridges BG/ISE/GLU/LAC of the affected lots may be discarded locally.



Communication of this Field Safety Notice

Please transfer this notice to other organizations/individuals on which this action has an impact. We sincerely apologize for any inconvenience caused by this issue and hope for your understanding and support.

Sincerely,

Roche Diagnostics Asia Pacific Pte Ltd

Email: sg.regulatory@roche.com




Appendix 1: Detection of the Sensor Lot and Serial Number

1) Lot and SN of a Sensor Cartridge BG/ISE/Glu/Lac - Lot 21560883 - SN 00200296




The lot number of an installed Sensor Cartridge can be checked in **cobas b** 123 system software under "Instrument > Consumable Status > Sensor Cartridge".






If this is an affected sensor from lot 21560883, the serial number of this Sensor Cartridge can be found in **cobas b** 123 system software under "Workplace>Instrument database> Results>Search".




Perform a search by "inserted"






Choosing the affected sensor lot and select detailed view:




The Serial Number will be shown on the display






Appendix 2: Deactivation of sodium (Na⁺)

Whenever you intend to use a **cobas b** 123 Sensor Cartridge of the affected lot 21560883 with SN 00200276 to SN 00200787, **the parameter sodium (Na⁺) must be deactivated. Deactivation** can be done under "Utilities > Configuration > Measurement > Parameter > Activ./deactiv." set Na⁺ to "OFF":




After selecting "Close", confirm the change by selecting "OK":





In the overview screen Na⁺ is then shown as greyed out, and the parameter is no longer active.





Re-activation of sodium (Na⁺):

Before the installation of a new, unaffected Sensor cartridge (lot number **different** from **lot 21560883** with **SN 00200276 to SN 00200787**), you can re-activate sodium under "Utilities > Configuration > Measurement > Parameter > Activ./deactiv." set Na⁺ to "ON":

