

Field Safety Notice

SBN-RTD-2018-002

RTD / Reagents

Version 1

10-Aug-2018

FLO-LOK III Dispenser Issues – Expanded Scope and Product

Product Name	FLO-LOK III Dispenser
Product Description	Reagent dispensers used on the BenchMark series of IHC/ISH instruments See below
GMMI / Part No Device Identifier	<i>Note: There may be other affected identifiers/lots that are affected globally. Please contact the product owner if the device is obtained from an overseas dealer.</i>
Production Identifier (Lot No./Serial No.)	See below
Type of Action	Field Safety Corrective Action (FSCA)

Product Name	GMMI Number	Expanded Affected Lots	Previously Communicated Lots
OptiView DAB IHC Detection Kit	06396500001	E00119	Y19271, Y11625, Y15571, Y24225
ultraView Universal Alkaline Phosphatase Red Detection Kit	05269814001	Y18053, Y22469	
ISH Protease 3	05273331001	Y13927, Y18872, Y25883	
VENTANA ISH iView Blue Detection Kit	05278511001	Y15105, Y22455	
ULTRAVIEW UNIVERSAL DAB DETECTION KIT	05269806001	None	Y09284, Y15384, Y18099, Y22153, Y11687, Y17984, Y19302, Y11716, Y18069, Y22147
OptiView Amplification Kit	06396518001	None	Y15435, Y19322, Y22447
Hematoxylin II	05277965001	None	Y10759, Y13938, Y17402, Y17403, Y21312, Y22561

FLO-LOK III Dispenser Issues – Expanded Scope and Product List

Dear Valued Customer,

Our records indicate that you received one or more of the products or lots on the expanded affected lots referenced above.

If your laboratory is utilizing same-slide controls as a routine practice, or uses assays in which a biologic internal control is always present (e.g. HER2 Dual ISH) or works with internal biological controls (e.g. CINtec PLUS) this failure mode was detectable and no look back is required. The affected products on the list above should not be used for clinical testing.

If you do not use these controls, please follow the directions per this FSN.

Description of Situation

In December 2017, Roche Tissue Diagnostics (RTD) issued a Field Safety Notification (FSN) in response to escalated complaints of leaking and sticking reagent dispensers. Roche initially attributed this failure to inadequate application of silicone oil to critical parts in the Horseradish Peroxidase (HRP) and Hematoxylin II dispensers. At that time, Roche initiated a root cause investigation.

The investigation confirmed that inadequate application of oil was the root cause. This occurred as a result of a change in manufacturing when moving from manual assembly of the dispensers to a fully automated reagent dispenser assembly (FARDA). Further, the investigation determined that the problem was not restricted to HRP and Hem II dispensers.

Two additional contributing factors were also identified:

1. Products intended for greater than 50 actuations
2. Products with emulsifiers

These two contributing factors, when combined, exacerbate the issue and its occurrence in the market.

Some products that meet the above criteria were not added to the list because they have no medical impact, and do not present a risk to patient safety (e.g. Hematoxylin II, Bluing, and RUO/Discovery products).

The root cause and contributing factors are consistent with customer complaint data. Based on this investigation we are expanding the list of affected products and lots.

The dispenser issues described above could result in a complete or partial dispense failure of a reagent critical to the staining reaction. This in turn could result in light or absent staining which, discounting any mitigations (e.g. use of same-slide controls), could cause diagnostic confusion, delay in diagnosis, or a false negative diagnosis.

In the worst case, a diagnostic error such as a false negative companion diagnostic assay (e.g. HER2) could lead to delay in treatment or inappropriate treatment that, depending on the duration of the delay, could impact patient survival.

FLO-LOK III Dispenser Issues – Expanded Scope and Product List

Actions taken by Roche Diagnostics

At the time of the initial FSN, all affected product that was in inventory was placed on hold. Further, in January 2018 RTD returned to previously established manual assembly of all dispensers.

RTD is now expanding the list of FARDA built affected products to include dispensers containing emulsifiers and those delivering over 50 actuations. Products in 50 actuation configurations, and those in any size without the presence of an emulsifier are not included in this expanded list.

RTD would like to emphasize the importance of following the instructions described in this letter in order to avoid and identify potentially erroneous results.

Actions to be taken by the customer/user

Customers should first determine if their laboratory has any affected product lots in inventory based on the “Expanded Affected Lots” column present in this notification. **If an affected product is found, it should not be used for clinical testing.** The lots in “Previously Communicated Lots” column are with reference to Field Safety Notice v2 (SBN-RTD-2017-001) dated 21-Dec-2017. Roche has already replaced these lots and no further actions will be required. The initial FSN required the use of same slide controls if affected product was to be used. This is because we did not have sufficient inventory of replacement product at that time. Newly manufactured products from the affected list are now readily available and should be used in place of affected product lots.

In the interest of patient safety and to identify potential diagnostic errors resulting from prior use of affected dispensers, Roche recommends a retrospective review and re-testing (if applicable) of clinical cases involving a dispenser included in the “Expanded Affected lots” column and in accordance with local hospital/laboratory procedures and policies. The ultimate scope of the re-testing is at the medical discretion of each laboratory, but should include at a minimum those assays used as the sole determinant for patient therapy or decision-making (e.g. HER2, ER/PR, ALK, PD-L1 (SP142), PD-L1 (SP263) and C-Kit (9.7)).

Review/re-testing is not necessary for:

- 1) laboratories utilizing same-slide controls as routine practice
- 2) assays in which a biologic internal control is always present (e.g. HER2 Dual ISH)
- 3) individual cases containing internal biologic controls
- 4) individual cases that were already re-tested in association with the original RTD field notification and re-testing recommendation (FSN-RTD-2017-001).

FLO-LOK III Dispenser Issues – Expanded Scope and Product List

Communication of this Field Safety Notice

This notice must be passed on to all those who need to be aware within your organization or to any other organization/individual where the potentially affected devices have been distributed/supplied. Please pass on this notice to the Chairman Medical Board and Head of Department as well, as required by HSA.

Please maintain awareness of this notice and resulting action for an appropriate period to ensure the effectiveness of the corrective action

We apologize for any inconvenience this may cause and hope for your understanding and your support.

Sincerely,

Roche Diagnostics Asia Pacific Pte Ltd

Email: sg.regulatory@roche.com