Ortho Clinical Diagnostics

IMPORTANT PRODUCT CORRECTION NOTIFICATION Unsuccessful Calibration using VITROS Immunodiagnostic Products NT-proBNP Reagent Packs, Lot 1620

Date

May 2017

Issue

This notification provides information regarding potential calibration failures when using VITROS NT-proBNP Reagent Packs, Lot 1620. Our records indicate that you were shipped the affected lot.

Affected Products

Product Name	Product	Affected Lot No.
(Unique Device Identifier No.)	Code	(Expiry Date)
VITROS Immunodiagnostic Products NT-proBNP Reagent Pack (10758750002061)	6802156	Lot 1620 (06-JUL-2017)

Investigation

Ortho Clinical Diagnostics (Ortho) confirmed that VITROS NT-proBNP Reagent Packs, Lot 1620 exhibited the potential for an increased frequency of calibration failures, with an increase in signal for the Level 1 calibrator causing a failure of the calibration parameters. Our testing indicates that the calibration failure is related to a component of the VITROS NT-proBNP Reagent Pack and is not associated with the VITROS NT-proBNP Calibrators.

Our investigation has confirmed that the increase in signal does not affect sample results (i.e., quality control or patient samples) within the 28 day calibration cycle.

Resolution

If your laboratory is able to successfully calibrate VITROS NT-proBNP Reagent Packs and your quality control results are acceptable; you may continue using your existing inventory.

To help ensure that future calibrations are successful, Ortho will send revised Master Calibration data.

NOTE: Current calibrations for these lots will become invalid after updating the Master Calibration data and <u>will require recalibration</u>.

For VITROS ECI/ECIQ Systems, the revisions are contained on a yellow Magnetic Lot Card.

<u>For VITROS 3600 or 5600 Systems</u>, the revisions are contained on Assay Data Diskette (ADD) DRV 5932 and above.

Upon availability, the ADD and yellow Magnetic Lot Cards will be sent in a separate notification.

Impact to Results

Previously reported patient results using Lot 1620 are valid providing that quality control results were within your acceptance range.

Required Actions

- If you are able to calibrate Lot 1620, implement the revisions on your system:
 - For VITROS ECI/ECIQ Systems: At your next scheduled calibration, scan the yellow Magnetic Lot Card for Lot 1620. Discard/destroy the original (green) Magnetic Lot Card that was shipped with the product.
 - For VITROS 3600, 5600 Systems: Install ADD DRV 5932 & above using the "Full Load" (All Assay Data) option. After loading the ADD for the first time, VITROS NT-proBNP Reagent Packs will become un-calibrated and will require recalibration. Following a successful calibration and quality control assessment, it is acceptable to use your remaining inventory.

NOTE: For e-Connected systems, download will be available by May 13, 2017.

- If you are unable to calibrate Lot 1620, when available, use the new Magnetic Lot Card or ADD DRV 5932 to calibrate.
- If you experience this issue and no longer wish to use this product, Ortho will credit your account for product discarded. Resubmit the Confirmation of Receipt form to indicate the quantity that requires credit.
- Post this notification by each system that processes VITROS NT-proBNP Reagent Packs.
- Complete the Confirmation of Receipt form and return by May 19, 2017.
- Forward this notification if you have distributed these products outside of your facility.

Contact Information

We apologize for any inconvenience this may have caused your laboratory. If you have questions, please contact your local Ortho representative or our Ortho Care $^{\text{TM}}$ Technical Solutions Centre at 1800 5646766.

Sincerely

Jon Wong, Quality Manager, 10 May 2017