

Urgent Customer Communication

Notice of potential leakage during procedure preparation due to cracked luer hub

Cordis® S.M.A.R.T.® Flex Vascular Stent System 85 lots across 48 catalog numbers- See listing in Table 1


November 15, 2017

Dear Valued Customer,

The purpose of this communication is to inform you of a potential leakage scenario with the S.M.A.R.T.® Flex Vascular Stent System. The leak may occur due to potentially cracked hubs in some units from within the 85 lots listed in Table 1.

| | |
|------------------------------------|---|
| <p>Correction Overview:</p> | <p>Based on one complaint and the subsequent investigation, Cordis has determined that 85 distributed lots of S.M.A.R.T.® Flex Vascular Stent System have a potential for cracked luer hubs, due to a manufacturing error.</p> <p>The luer hub is used to inject contrast/saline during procedure preparation, prior to insertion of the stent system into the patient. A cracked hub could result in leakage of saline, or in the worst case, inability to flush the outer sheath of the catheter.</p> <p>The potential medical consequence would be a delay in device preparation, resulting in the need to prepare a replacement device for use. Cordis does not anticipate any other patient impact.</p> <p>Cordis would therefore like to emphasize the following steps already contained within the Instructions For Use:</p> <p style="text-align: center;"><i>Use a 1-3 cc syringe to flush the outer sheath (1) with sterile heparinized saline through the female luer (4) on the handle. Flush until only a few drops of saline exit the distal end of the outer sheath. Complete system flushing may require 2-3 flushings with a 1cc syringe.</i></p> <p style="text-align: center;"><i>Warning: If the outer sheath (1) cannot be flushed do not use the device.</i></p> <p>There is no safety concern for patients that are treated successfully using product from these lots.</p> <p>This is a customer communication only. This is not a removal.</p> |
|------------------------------------|---|

| | |
|---|---|
| <p>Details on Affected Devices, to assist in identification of the product involved:</p> | <p>Product involved</p> <ul style="list-style-type: none"> • 85 lot numbers of 48 catalog numbers. Reference Table 1. The lot number range is from 40932 through 41637, but not all lots in the range are affected. • The newest lot involved has a Use By Date of 2019-04-26. • Although it is possible that some additional uninspected units in the supply chain will be distributed, most additional units from the affected lots distributed in the future will have been inspected and confirmed to be free of visible cracks at the luer hub. <p>Identification</p> <p>The following photos are provided to help you identify the S.M.A.R.T.® Flex Vascular Stent System. Affected lots are identified by the Lot number on the carton and pouch.</p> |
|---|---|




Usage (to assist in identification of where devices are kept in facility)

The S.M.A.R.T. ® Flex Stent iliac indication is intended for use in the common and external iliac arteries to improve luminal diameters in patients with symptomatic vascular stenotic and/or occlusive diseases.

The S.M.A.R.T. ® Flex Stent superficial femoral artery and proximal popliteal indication is intended as a treatment for atherosclerotic superficial femoral artery lesions and proximal popliteal lesions.

| | |
|---|---|
| <p>Actions requested on your part:</p> | <ol style="list-style-type: none"> 1) Read the “Description of the problem” section carefully to fully understand the issue involved. 2) Check your inventory to determine if you have any remaining affected product in your possession. Check all storage and usage locations. The purpose is to identify the product, not to remove the product. 3) Keep a copy of this notice with any affected product. Due to low severity of the condition, a formal acknowledgement is not requested. 4) Share this letter with anyone who needs to be informed in your facility, or in any facility where potentially affected devices may have been transferred. 5) During procedure preparation, check for cracks/leaks. If the user detects a crack prior to flushing, or a leak during flushing, select a replacement device. (See inspection section below.) Report the incident through the standard complaint process. 6) Maintain awareness of this notice until all affected product has been consumed. |
|---|---|

| | |
|---|--|
| <p>Description of the problem:</p> | <p>What is the summary of the issue? Due to a manufacturing error, some luer hubs in the affected lots may have cracks. Most of the cracks observed in the investigation were minimal, resulting in slight leakage of saline, but the degree of cracking varies.</p> <p>What are the health consequences if product with a cracked hub is used? Pre-procedural delay: Devices are prepared for use in advance of the start of the procedure. At that time, in accordance with the IFU, the user prepping the devices should readily identify a leakage scenario, resulting in a pre-procedural delay and no consequence to the patient.</p> <p>Catheterization Lab personnel are highly trained in identifying and mitigating hazards associated with these medical devices. Exchange and preparation of a replacement unit is conducted efficiently; therefore, there should be minimal intra-procedural delay.</p> <p>There is no safety concern for patients that are treated successfully using product from these lots.</p> |
|---|--|


| | |
|-------------------------------------|--|
| Inspection details: | <p>As stated in the Instructions for use, users are warned that the device should not be used if the outer sheath cannot be flushed. Inspect for leakage during preparation of the device. Leakage may be more likely in the affected product due to cracks in the luer. At time of actual flushing, if there is no leakage observed, the product may be safely used.</p> <p>For reference, cracks, when present, are visible in the region indicated in the photo below.</p>  <p>A noted above, it is possible that some additional uninspected units in the supply chain will be distributed. However, most additional units from the affected lots distributed will have been inspected and confirmed to be free of visible cracks at the luer hub.</p> |
| Why you are being contacted: | <p>You are receiving this letter because our records indicate that you have received one or more of the affected lots.</p> |

| | |
|------------------------------|---|
| Available Assistance: | <p>If you have any questions regarding this information please contact your local sales representative or local sales office.</p> |
|------------------------------|---|

| | |
|--------------------------------|---|
| Additional Information: | <p><u>What other action is Cordis taking?</u></p> <p>Cordis has performed a root cause investigation and taken immediate corrective action. There are no other lots involved in that other lots were either already inspected for the condition after manufacture or not manufactured in the time frame of the manufacturing error. Cordis is voluntarily taking this action.</p> <p><u>Regulatory Notification</u></p> <p>This communication is not considered a Field Safety Corrective Action as defined in the EU Guidelines on a Medical Devices Vigilance System (MEDDEV 2.12-1 rev 8). Therefore, notification to EU regulatory bodies does not apply.</p> |
|--------------------------------|---|

We apologize for any inconvenience this communication may cause. We know that you place high value in our products and we appreciate your cooperation in this matter. Cordis is committed to maintaining your confidence in the safety and quality of the products that we supply.

Respectfully yours,



Miguel Ávila
Vice President, Global Quality and Regulatory Compliance
Cordis Corporation

Table 1- **Cordis® S.M.A.R.T.® Flex Vascular Stent System Impacted Lots**

| GTIN | Catalog | Lot Number | | | | | |
|----------------|-----------|------------|-------|-------|-------|-------|-------|
| | | | | | | | |
| 20705032066980 | SF05060MV | 41064 | 41191 | 41327 | | | |
| 20705032066720 | SF05060SV | 41065 | | | | | |
| 20705032067123 | SF05080MV | 41303 | 41328 | | | | |
| 20705032066881 | SF05080SV | 41059 | | | | | |
| 20705032066614 | SF05100MV | 41109 | | | | | |
| 20705032066751 | SF05100SV | 41192 | | | | | |
| 20705032066362 | SF05120SV | 41460 | | | | | |
| 20705032066492 | SF05150MV | 41066 | 41067 | 41330 | | | |
| 20705032066386 | SF05150SV | 40940 | 41331 | | | | |
| 20705032066430 | SF06030MV | 41110 | 41462 | | | | |
| 20705032066676 | SF06040MV | 41332 | 41463 | 41464 | 41465 | | |
| 20705032066997 | SF06060MV | 41304 | 41333 | | | | |
| 20705032067031 | SF06060SV | 40932 | 41060 | | | | |
| 20705032066898 | SF06080MV | 41007 | 41014 | 41061 | 41111 | 41112 | 41335 |
| 20705032066737 | SF06080SV | 41012 | 41113 | | | | |
| 20705032066621 | SF06100MV | 40941 | 41193 | 41337 | | | |
| 20705032066560 | SF06120MV | 41194 | 41339 | | | | |
| 20705032066775 | SF06120SV | 41190 | 41468 | | | | |
| 20705032066577 | SF06150MV | 40938 | 41340 | 41341 | | | |
| 20705032066485 | SF06150SV | 41342 | | | | | |
| 20705032066683 | SF07040MV | 41343 | | | | | |
| 20705032067185 | SF07040SV | 40935 | 41306 | | | | |
| 20705032067000 | SF07060MV | 41469 | | | | | |
| 20705032066973 | SF07060SV | 41015 | | | | | |
| 20705032066904 | SF07080MV | 41116 | 41346 | | | | |
| 20705032067116 | SF07080SV | 41307 | 41308 | | | | |
| 20705032066638 | SF07100MV | 41008 | 41347 | | | | |
| 20705032066478 | SF07100SV | 41300 | | | | | |
| 20705032066911 | SF07120MV | 41473 | 41474 | | | | |
| 20705032066782 | SF07120SV | 41013 | | | | | |
| 20705032066508 | SF07150MV | 41475 | | | | | |
| 20705032066935 | SF07150SV | 41005 | | | | | |
| 20705032066843 | SF07200MV | 41016 | 41195 | | | | |
| 20705032066584 | SF08040MV | 41068 | 41071 | 41591 | | | |
| 20705032066669 | SF08040SV | 40936 | 41348 | | | | |
| 20705032067086 | SF08060MV | 41476 | | | | | |
| 20705032066454 | SF08080MV | 41350 | | | | | |
| 20705032066744 | SF08080SV | 41312 | 41351 | 41637 | | | |
| 20705032066416 | SF08200MV | 41118 | | | | | |
| 20705032066549 | SF09020MV | 40933 | | | | | |
| 20705032066850 | SF09030MV | 41017 | 41062 | | | | |
| 20705032066706 | SF09060MV | 41019 | | | | | |
| 20705032066966 | SF09060SV | 41009 | 41196 | | | | |
| 20705032067109 | SF09080MV | 41006 | | | | | |
| 20705032066461 | SF09100SV | 41011 | | | | | |
| 20705032066119 | SF10020SV | 41183 | | | | | |
| 20705032067055 | SF10030MV | 41120 | | | | | |
| 20705032067154 | SF10100MV | 41070 | | | | | |