



### MEDICAL DEVICE FIELD SAFETY CORRECTION

2017-02-06

To: contact@sindor.com

RE: Notification of Error Correction in Instructions for Use

Dear Valued Customer,

PENTAX Medical has become aware of an error in the description of an Instructions for Use of ULTRASOUND UPPER GI VIDEO SCOPES EG-3870UTK, EG-3670URK. Please ensure that all potential users in your facility are made aware of this safety notification and the recommended actions.

#### Affected Product details:

ULTRASOUND UPPER GI VIDEO SCOPES EG-3870UTK, EG-3670URK

Number of Instructions for Use:

Z845

Revision No.:

R13-R14

# Safety issue:

## **WARNING**

The errors in the instructions for use (IFU) shown in the following table are corrected in the right column. Following to the erroneous description in the IFU may result in ineffective reprocessing, posing a risk of cross-contamination.

## Safety Instructions:

Although no incidents have been reported, please be informed about the following errors and correction:

Page	Error	Correct
p70	WARNING:	WARNING:
	The cleaning detergent solution should	The disinfecting solution must remain in
	remain in contact with the ALL internal	contact with the ALL internal channels and
	channels and external endoscope	external endoscope surfaces for the time
	surfaces for the time period recommended	period recommended by the manufacturer
	by the manufacturer of the disinfectant.	of the disinfectant.

### Contact information:

Please feel free to contact at:

Tel: 6507 9266

Fax: 6271 1691

Email: vigilanceAsia@pentaxmedical.com

We sincerely regret any inconvenience caused by this action and appreciate your immediate attention to this matter.

Please be assured that maintaining a high level of safety and quality is our highest priority.

If you have any question regarding this action, please feel free to contact your local office of PENTAX Medical.

