

30 Mar., 15

# RE: Product Recall - CN10 GENTAMICIN (CT0024B)

Dear Customer,

Please be informed of the product recall of the batches below.

### 1. Item(s) affected

Product: CT0024B CN10 GENTAMICIN

Batch: 1580419

#### 2. Reason for recall

A technical investigation has indicated that this lot of **Oxoid Antimicrobial Testing Disc, CT0024B CN10 Gentamicin, Lot 1580419** may contain discs that have insufficient concentration of antibiotic. Continued use of this lot could result in false resistance reporting.

### 3. Actions to be taken

- Please discontinue any usage and destroy any unused or partially used inventory.
- Kindly fill up the acknowledgement section below and send back to us for us to arrange for replacement or credit.
- Review results reported using this lot and consider retesting and/or seek appropriate expert advice.

Please refer to attached memo for more information and feel free to contact us should you have any queries regarding this recall.

Thank you for your prompt attention.

Yours Sincerely,

Ji Wenxin

Tel: +65 64999992

Email: wenxin.ji@thermofisher.com

# Acknowledgement (To be completed by end-user customer)

I confirm that the affected batch has been destroyed.
I requirereplacement packs (please indicate if none required).
Signed
Name (please print)
Position
Date
Email Address/Telephone Number
Company Name & Stamp:

Microbiology

Blk 33 Marsiling Industrial Estate Road 3 #07-06 Singapore 739256 +65 6499 9999 tel +65 6896 2147 fax www.thermofisher.com



Thermo Fisher Scientific Microbiology Wade Road Basingstoke Hampshire RG24 8PW

Phone: +44 (0) 1256 841144 Fax: +44 (0) 1256 814626 www.thermoscientific.com



27th March 2015

### **URGENT FIELD SAFETY NOTICE**

## Oxoid Antimicrobial Testing Disc, CT0024B, CN10 Oxoid Gentamicin, Lot 1580419

Customers are to be advised of the following:

A technical investigation has indicated that this lot of Oxoid Antimicrobial Testing Disc, CT0024B CN10 Gentamicin, Lot 1580419 may contain discs that have insufficient concentration of antibiotic.

Continued use of this lot could result in false resistance reporting.

Customers should review their internal quality control and test results reported using these lots and consider retesting and/or seek appropriate expert advice.

Accordingly, in keeping with our Quality Policy, we request that you destroy any remaining inventory of the lot listed above and contact Customer Services of your local Oxoid supplier who will issue a replacement.

This notice needs to be passed on to all who need to be aware within your organisation.

The Medicines and Healthcare products Regulatory Agency (MHRA) have been informed of this Field Safety Corrective Action.

If you experience any problems complying with this notice or you require any further information, please contact our Technical Support Department on +44 (0)1256 694238, or at <a href="mailto:microbiology.techsupport.uk@thermofisher.com">microbiology.techsupport.uk@thermofisher.com</a>

Yours Sincerely,

Colin Booth

Global Director, Quality Assurance and Regulatory Affairs, Microbiology Products