CC. Chairman Medical Board and relevant Head of Departments



To all users of a SIEMENS SOMATOM Definition Flash, AS or Edge with software version VA48A_SP1 or VA48A_SP2 without injector license

Name Department

Telephone E-mail Date Chua Link Soon Head of CS + 65 6490 8880

linksoon.chua@siemens.com

Customer Information Letter CT019/16/P

 Re: Bug Fixes for SOMATOM Definition Flash, AS or Edge with software version VA48A_SP1 or VA48A_SP2 without injector license

Dear Customer,

This letter is to inform you of the release of a software update that provides bug-fixes to improve system performance for customers using

SOMATOM Definition Flash SOMATOM Definition AS SOMATOM Definition Edge

We thank you for your cooperation.

with Software Version VA48A_SP1 or VA48A_SP2 without injector license

Customers with Software version VA48A_SP1 or VA48A_SP2 without injector license will be provided an update to Software version VA48A_SP3. The installation of this update will address software bugs that were identified through field monitoring. Please note: For VA48A_SP1 it is regardless if injector licenses are in use.

The update will be remotely pushed to the system or our service organization will contact you to arrange a date for the installation of the software update on site. Please feel free to contact our service organization for an earlier appointment.

We advise that you notify anyone at your organization that should be aware of this information. If the device has been sold and therefore no longer in your possession, please forward this information notice to the new owner. We would also request that you inform us of the identity of the device's new owner where possible.

| With best regards, | |
|--|---|
| | |
| Chua Link Soon Head of Customer Service | Lai Pai Lin Head of Quality Technology |

Restricted